

VEHICLE INSPECTION REPORT

PJ66BCF

Daf LF 45.150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	24/10/2016	Colour	RED	Gearbox	MANUAL
Year	2016	VIN	XLRAEL1500L459118	Axle Combi	4x2
Mileage	812,712 Km Warranted	Body Style	Box Van	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	30/09/2026	Tail Lift	Cantilever
GVW	7500kg	Cab Type	DAY CAB		

NON-RUNNER - CAT/SCR - NOT DRIVEABLE, OIL PRESSURE LOW, ENGINE POWER REDUCED, LEAKING HYDRAULIC FLUID WHEN OPERATING TAIL LIFT - WILL NEED TO BE STRAPPED DOWN ON COLLECTION, WARNING LIGHTS ON DASH




Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm

2: Bonnet
Chipped
Multiple Chips



3: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace

6: Door nsf
Chipped
Multiple Chips



7: Door osf
Chipped
Multiple Chips

8: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



9: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint

10: Moulding osf Wing
Broken
Replace



11: Bumper Front
Scratched
Over 100mm Thru Paint

12: Seat Base Cover nsf
Holed
Over 3mm



13: Fascia Trim
Missing
Replace

14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		