

# VEHICLE INSPECTION REPORT

**RIG5385**

## Daf XF 510

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 14/06/2016

Year 2016

Mileage 905,578 Km Not Warranted

Fuel Type Diesel

Colour BLUE

VIN XLRTGH4300G111119

Body Style Tractor Unit

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

\*WARNING LIGHT ON DASH\* LIGHT WEIGHT AXLE, SLIDING 5TH WHEEL, TWIN FUEL TANK

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



## Features

- Navigation system
- Air conditioning

## Photos










## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
UpTo 25mm Thru Paint



2: Screen Front  
Chipped  
UpTo 10mm




3: Fog Lamp Surround os  
Scratched (Painted)  
UpTo 25mm Not Thru Paint



4: Bumper Front  
Scratched  
UpTo 25mm Not Thru Paint



5: Door Mirror Assy nsf  
Broken  
Replace



6: Other  
N/A  
N/A



7: Other  
N/A  
N/A



8: Other  
N/A  
N/A






9: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Not Thru Paint



10: Door osf  
Chipped  
Edge Chip



11: Other  
N/A  
N/A



12: Seat Back Cover osf  
Holed  
Over 3mm



13: Seat Base Cover osf  
Holed  
Over 3mm



14: Other  
N/A  
N/A



15: Other  
N/A  
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	Fault
ABS light illuminated	OK		Service indicator light illuminated	OK