

VEHICLE INSPECTION REPORT

SA71KJJ

Fiat Doblo Work Up 16V II 1.6 MULTIJET

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow

Details

Reg. date	22/11/2021	VIN	ZFA26300006V30339	CAP Below	£4,625.00
Year	2021	Body Style	Dropside L2	Gearbox	MANUAL
Mileage	92,867 Miles Warranted	MOT Due	17/09/2026	Gears	5
Fuel Type	Diesel	CAP Clean	£6,075.00		
Colour	WHITE	CAP Average	£5,550.00		

AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Door nsf
Dented
Over 30mm



4: Qtr Panel nsr
Dented
Over 30% Of Panel



5: Lamp nsr
Broken
Replace



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Cracked
Replace



8: B Post os
Dented
With Paint Damage



9: B Post os
Scratched
Over 25mm Thru Paint



10: Door Mirror Assy osf
Broken
Replace



11: Wing osf
Scratched
Over 25mm Thru Paint



12: Wing osf
Rusted
Over 5mm



13: Door Pad osf
Broken
Replace



14: Switches And Controls
Broken
Replace



15: Fascia Panel
Missing
Replace




16: Seat Base Cover osf
Torn
Over 3mm



17: Carpets Front
Holed
Over 3mm



18: Seat Base Cover nsf
Torn
Over 3mm



19: Fascia Panel
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		