

# VEHICLE INSPECTION REPORT

**SB15XHR**

## Vauxhall Vivaro 2900 1.6CDTI BiTurbo 120PS ecoFLEX

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 03/06/2015

Year 2015

Mileage 93,816 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN W0L2F7118FV629795

Body Style Panel Van LWB

Keys 2

MOT Due 25/01/2026

CAP Clean £2,700.00

CAP Average £2,225.00

CAP Below £1,625.00

Gearbox MANUAL

Gears 6

Doors 2

Steering Combi Standard Axle

Rear Suspension Steel

SINGLE SIDE DOOR

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Rusted  
Over 5mm



2: Wing of  
Rusted  
Over 5mm



3: Door osf  
Dented  
Over 2 UpTo 10mm



4: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



5: Tailgate  
Dented  
Over 30mm



6: Bumper Rear Moulding  
Scuffed (Unpainted)  
UpTo 100mm



7: Door nsr  
Dented  
Over 30mm



8: Door nsf  
Dented  
Over 2 UpTo 10mm



9: Wing nsf  
Rusted  
UpTo 5mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK